



Bangladesh Accreditation Board (BAB)

91, Motijheel C/A, Dhaka-1000, Tel: +880-2-9513221 Fax: +880-2-9513222

Email: info@bab.org.bd Web: www.bab.org.bd

Certificate of Accreditation

This is to certify that


Inspection Service Division, ITS Labtest Bangladesh Limited

Phoenix Tower (2nd & 3rd Floor)

407, Tejgaon I/A, Dhaka-1208, Bangladesh

has been granted accreditation in respect of the scope of accreditation described in the attached document, subject to the terms and conditions governing the relevant Conformity Assessment Body (CAB) accreditation

This Inspection Body (Type-A) having met the requirements of ISO/IEC 17020:2012 and the BAB, is accredited for Textile & Textile Products Inspection as described in the associated Scope of Accreditation.



Certificate Number : 05.004.18

Issued on : 31 December 2018

Accreditation Date : 31 December 2018

Valid until : 30 December 2021

**Md. Monwarul Islam
Director General**

Bangladesh Accreditation Board (BAB)

This certificate has been issued under the authority of Bangladesh Accreditation Act, 2006 and must be returned on request; reproduction must follow guidelines in place at date of issue. For the specific scopes to which this accreditation applies, please refer to the directory of accredited CABs at <http://www.bab.org.bd/directory-of-accredited-cabs>

SCOPE OF ACCREDITATION

(For Inspection Bodies)

CAB Name & Address:	ITS Labtest Bangladesh Ltd. (Inspection Division), Phoenix Tower (2nd & 3rd Floor), 407, Tejgaon Industrial Area, Dhaka, Bangladesh		
Accreditation Standard:	ISO/IEC 17020:2012	Accreditation Date:	31-Dec-2018
Certificate Number:	05.004.18	Issued on:	31-Dec-2018
Last Amended on:	NA	Valid until:	30-Dec-2021
Amendment no:	NA		
Types :	A		

Head Office or primary location			Additional Locations (If different from Head Office)		
Phoenix Tower (2nd & 3rd Floor), 407, Tejgaon Industrial Area, Dhaka, Bangladesh			1	NA	
			2	NA	
			3	NA	
Type (A,B,C)	Inspection Category(Product , Process, Services or Installation)	Inspection Field (and sub-fields)	Range of inspections	Stage of inspection	Inspection requirements or criteria
A	Product	Apparel/ Home textile	NA	During Production Inspection (DPI) Final Random Inspection (FRI) Fabric Inspection	AQL table ISO 2859-1:1992 Standard Test Methods for Visually Inspecting and Grading Fabrics: ASTM D5430 – 13 ITS-WI-004-GLOBAL R00 General inspection procedure for FRI ITS-WI-006-GLOBAL R00 General Inspection Requirement for Softlines and Customer requirements

END



Quality Manager